



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1965

Work Order Type: Weatherization

Audit Name: 14014SO1965

CLIENT INFORMATION

Client Name:

Client ID: 14014SO1965

Alt. Client ID: WAYNE

Address: , Unit 977

WAYNESBORO, TN 38485

AGENCY INFORMATION

Agency: South Central Human Resource Agency

Address: (PO Box 638) 1437 Winchester Highway
Fayetteville, TN 37334

Agency Phone: (931) 433-7182

Fax: (931) 433-0074

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 14014SO1965

Alt. Client ID: WAYNE

Work Order (Bid Form)

Work Order Name: 14014SO1965

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 4

Measures

Measure 1 General Air Sealing

Components

Inspected

Comment

SEAL HOME WHERE IT IS PUT TOGETHER SEAL ALL REGISTERS AND
RETURN WITH MASTIC INSTALL FRONT DOOR UNIT WITH S/D INSTALL
BACK DOOR UNIT
REPLACE APPROX 40 SQ FT OF BELLYBOARD

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing (setup cost)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Miscellaneous Su	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		

Field Notes:

Measure 2 Replace Heating [Electric]

Components

Inspected

Comment INSTALL SPLIT UNIT HEATPUMP 85 PERCENT EFFICIENT TO SERVICE
2280 SQ FT

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipme	Replacement elec furnace (not used)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Replacement elec furnace (not used)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		

Field Notes:

Client Name:

Client ID: 14014SO1965

Alt. Client ID: WAYNE

Work Order (Bid Form)

Work Order Name: 14014SO1965

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 4

Measure 3 Fix Improper Venting (Clothes Dryer)**Components****Inspected**

Comment Vent to exterior and cap as per 2.5.4 of SWFG (pages 2-17 and 2-18).
INSTALL 2 DRYER VENTS METAL FLEX

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Exterior Cap / Metal Flex / Clamps	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:**Measure 4 Smoke CarbonDetector is Needed****Components****Inspected**

Comment SMOKE CARBON DETECTOR

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke carbondetector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:

Client Name:

Client ID: 14014SO1965

Alt. Client ID: WAYNE

Work Order (Bid Form)

Work Order Name: 14014SO1965

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 4

**Measure 5 Vapor Barrier Needed
(Basement/Crawlspace)****Components****Inspected**

Comment Install 6 mil poly as ground cover. Over laps should be at least 6". Lap up foundation walls and piers 6" and seal. See page 3-29 of SWFG.

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement / crawlspace vapor barrier	SqFt	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	SqFt	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 14014SO1965

Alt. Client ID: WAYNE

Work Order (Bid Form)

Work Order Name: 14014SO1965

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 4